# Navajo Abandoned Uranium Mine

## **Site Screen Report**

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

## **Black Point-Murphy Group AUM Site**

Navajo AUM Western Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.599.1111

January 2011

Part I	Site Identifica	ation, Location	and Status			
Site Names and ID numbers as applicable						
Mine ID:	463					
Map ID:	W107					
CERCLIS:	NNN0009091	11				
Navajo Aban	doned Mine L	and Reclamati	on Program: None	e		
Local name / Aliases: Murphy No. 1-17; Murphy Mine; Black Point						
Chapter and local area: State of Arizona						
County: Coc	onino	State: Arizon	a			
Lat/Long: 35	5.7078920818 N	N / -111.312504	877 W			
Nearby road	and highway:	Highway 89	Local Post	Office: Cameron, AZ		
Surface Land below	Status: check	one or more a	and provide owners	hip and contact information		
Tribal Trust Private Bureau of La State			Public lands Tribal Fee Land Allotment Fee land			
Subsurface M	Iineral Rights:	:				
No information on subsurface mineral rights ownership was found in the EPA/AUM Database						
Claim and op	erator inform	ation:				
showed the op	erator of the m	ine as Howell a	and Glassock in 1956	nd. Historical documents 6, and Howell, Sheppard, and s identified in the EPA/AUM		
Number of re	sidential struc	tures within 2	00 feet of mine: N	Ione		
Estimated vol	lume of mine v	waste onsite:	None			

## Part II Summary of radiological readings

#### **Highest gamma radiation measurement:**

28,224 counts per minute (cpm)

### Describe any other radiological measurements:


A total of 3,370 gamma radiation measurements were collected from the mine site, ranging from 8,064 cpm to 28,224 cpm. The measurements collected at the site and pond 0.15 mi north of the site were found at background levels, but measurements collected from an isolated hot spot along the road 0.4 miles north of the site were found at a maximum level of 50,000 cpm. The measurements are represented in Figures 1 and 2.

**Background Readings:** 11,605 cpm

**Background Average:** 11,605 cpm

#### **Distribution Chart and Statistics:**

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 3370

 Minimum:
 8064,00000

 Maximum:
 28224,00000

 Sum:
 42889246,00000

 Mean:
 12726,77923

 Median:
 12383,00000

 Standard Deviation:
 2244,39889

#### Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Unknown Waste Pile onsite: No

**NAMLRP Project Number:** None

NAMLRP Mine features: None

The following information was obtained from field observations collected during the 2010 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed	reclamation	work and	ctatuc.
COUNCI VCU	i cciainauvii	wui K anu	Status.

#### **Adits**

None

#### **Waste Piles**

None

#### **Pits**

None

#### Shafts

None

## **Other Debris and Mine Features**

Fenced in area in NW portion of site

#### Part IV

#### Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

**0 to 200 feet:** None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

**200 feet to 0.25 mile:** Gravel mine approximately 0.25 mi N of site

Levels measured around the perimeter(s) of the identified structure(s):

Background levels near gravel mine and pond, road 0.25 mi N of gravel mine had a small section up to 50,000 cpm

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

**0 to 0.25 miles:** Pond associated with gravel mining pit approximately 0.15 mi N of the site, all levels background; Little Colorado River Basin adjacent to the E of the site

0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

Little Colorado River Basin adjacent to the E of the site, possible wetlands

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Black Point-Murphy Group mine consists of an area of 28,976.73 m<sup>2</sup>. The mine was identified as being operational from 1956 to 1958. Historical documents showed the operator of the mine as Howell and Glassock in 1956, and Howell, Sheppard, and Bosley in 1958. While operational, the mine had a total production volume of 1,769 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

## Part V Response Action Summary

## **Summary of Evaluation Factors:**

## Accessibility:

Was the mine easily accessible to potential human activity? Yes

## Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

No

#### Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? No

#### Structures:

Were any structures observed within 200 feet of the mine?

No

## Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine? Yes

#### Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Unknown (there is a fenced in area in the NW portion of the site)

## Part VI Photos



Photo 1. Black Point-Murphy Group mine site



Photo 2. Black Point-Murphy Group mine site



Photo 3. Black Point-Murphy Group mine site, fenced in area



Photo 4. Black Point-Murphy Group mine site, alongside Little Colorado River Basin



Photo 5. Black Point-Murphy Group mine site, alongside Little Colorado River Basin



Photo 6. Black Point-Murphy Group, pond associated with gravel mine 0.15 mi north of site



Photo 7. Black Point-Murphy Group, road with elevated gamma readings, 0.4 mi north of site

Name:

## Part VII Contacts Reports and Information

Stanley Edison (928) 871-6861

Eugene Esplain (928) 871-7331				
Title or official role (if any) Navajo EPA Superfund Program				
Address PO Box 2946, Window Rock, AZ 86515				
Information provided <u>Lead Regulatory Agency</u>				
Name				
Title or official role (if any)				
Address				
Telephone number				
Information provided				
Name				
Title or official role (if any)				
Telephone number				
Information provided				
Name				
Title or official role (if any)				
Telephone number				
Information provided				

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Black Point-Murphy Group (463)
Coconino County, Arizona






Figure 2 - Gamma Radiation Measurements Black Point-Murphy Group (463) Coconino County, Arizona



### **Gamma Radiation Measurements**

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000



Gamma survey conducted 11/2010 Measured as counts per minute (cpm)

Average background 11,605 cpm

